

<i>Description</i>	<i>Product ID</i>	<i>Melt Point</i>	<i>Plasticizers</i>	<i>Home Wash</i>	<i>Industrial Wash</i>	<i>Dry Clean</i>	<i>Polyester</i>	<i>Polycotton</i>	<i>Nylon</i>	<i>Lycra</i>	<i>ABS</i>	<i>Polycarbonate</i>	<i>Polypropylene</i>	<i>PVC</i>	<i>Polyurethane</i>	<i>Wood</i>	<i>Leather</i>	<i>Rubber / Neop.</i>	<i>Fiberglass</i>	<i>Aluminum</i>	<i>Copper</i>	<i>Steel</i>
PSA / REINFORCEMENT TAPE	PSA 100	N/A					◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆
	PSA 105	N/A					◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆	◆
	PAF-120 L	230° - 250° F 110° - 120° C	◆	◆		◆	◆	◆				◆		◆		◆	◆		◆	◆	◆	◆
	RAF-300	260° - 280° F 130° - 140° C	◆	◆		◆	◆	◆				◆		◆	◆	◆	◆	◆	◆		◆	◆
	RAF-310	260° - 280° F 130° - 140° C	◆	◆		◆	◆	◆				◆		◆	◆	◆	◆	◆		◆	◆	◆
	RAF-320	260° - 280° F 130° - 140° C	◆	◆		◆	◆	◆				◆		◆	◆	◆	◆	◆		◆	◆	◆